ECS/EMD Configuration Change Request

1. Originator	2. Log Date:	3. CCR #:	4. Rev:	5. Tel:	6. Rm #:	7. Org.
Sarah Lewallen	**7/21/04**	**04-0379**	**—**	301-925-0865	3103A	COTS HW

8. CCR Title: Upgrade the internal drive in t1mss04 to support baseline update

9. Originator Signature/Date	10. Class	11. Type:	12. Need Date: 7/30/04
Sarah Lewallen /s/ 7/21/04	**II**	**CCR**	

13. CCR Sponsor Signature/Date	14. Category of Change:	15. Priority: (If "Emergency" fill in Block 27).
Pamela Johnson /s/ 7/21/04	Update ECS/EMD Baseline Doc	Routine

16. Documentation/Drawings Impacted *(Review and submit checklist):* 920-TDV-001	17. Schedule Impact: None	18. CI(s) Affected: MSSHW

19. Release Affected by this Change: N/A	20. Date due to Customer:	21. Estimated Cost: None - Under 100K

22. Source Reference: ☐NCR (attach)   ☐Action Item   ☐Tech Ref.   ☐GSFC   ☒Other:
Solaris 8 baseline update

23. Problem: (use additional Sheets if necessary)
t1mss04 has a 2GB root disk.

24. Proposed Solution: (use additional sheets if necessary)
Upgrade t1mss04 root disk with a 9GB drive. Configure with 4GB partition for root and 1 GB swap. Clone existing root to 9GB drive, then upgrade the baseline patches.

25. Alternate Solution: (use additional sheets if necessary)
None

26. Consequences if Change(s) are not approved: (use additional sheets if necessary)
Will not be able to upgrade t1mss04 to new Solaris 8 baseline.

27. Justification for Emergency (If Block 15 is "Emergency"):

28. Site(s) Affected: ☐EDF   ☐PVC   ☒VATC   ☐EDC   ☐ GSFC ☐LaRC   ☐NSIDC   ☐SMC   ☐AK ☐JPL
☐EOC   ☐ IDG Test Cell   ☐Other

29. Board Comments:	30. Work Assigned To:	31. CCR Closed Date:

32. SCDV CCB Chair (Sign/Date): **Byron V. Peters /s/ 07/22/04**	Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS
33. EDF CCB Chair (Sign/Date):	Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS
34. ECS CCB Chair (Sign/Date):	Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ESDIS